


Design and production of fine quality laser cut models and components



Cable Drum
(Loaded)



Instructions

Lay out the parts supplied to familiarise yourself with them.





To assemble this kit you will require a good quality PVA adhesive. A cocktail stick or similar may be useful with alignment to begin with.



1



2



3



4



5

