



Design and production of fine quality laser cut models and components



Jackdaw Hovel

Instructions

Lay out the parts supplied to familiarise yourself with them.




To assemble this kit you will require a good quality PVA adhesive and a craft knife or scalpel for cutting tabs on some parts. You may also find the aid of a pair of tweezers useful.



Note:

These parts should be located to the depth of the base






2


















Be sure to observe alignment and gap on right hand side. This is to allow movement of window and glazing when fixing in later steps.







5





As with step 4.





6



















Release by cutting tab







22 23









Note:

Crack in brick is a guide to placement.


















34 35






Fix roof battens to both sides of the roof noting alignment.









Identify roof tile sheet for the left side of the roof and note where the top edge of the first row should be located.






















Enjoy your model!